




date client project

TLX ref

The TLX Gold solution: 100mm rafters breathable roof



- Remove tiles, tile battens and old felt.
- Fit 50mm 0.032 W/m K Mineral Wool closely between rafters
- Drape TLX Gold into remaining rafter space, creating a 10mm unventilated air space.
- Fit tile battens, then tiles or slates

Renovated roof $U = 0.39 \text{ W/m}^2 \text{ K}$

Building Regulation compliance

Approved Document L1B states that:

- When a house is being re-roofed, or at least 50% is being repaired there is a requirement to improve the thermal performance. The required U-value for a pitched roof is 0.18 W/m² K. Where it is not reasonably practicable to achieve this, improvement to achieve a 15-year pay back period should be accepted.
- In the case of a roof that is a retained thermal element, it is only necessary to upgrade the thermal performance if it does not meet a threshold value of 0.35 W/m² K. If it is not feasible to upgrade to the required standard, a lesser performance should not be worse than 0.7 W/m² K.

Payback

Payback time for the insulation has been estimated as 2.9 years based on a simple 1970s room in a roof house, with an existing pitched roof containing no insulation, which is upgraded using TLX Gold as described

Condensation Risk see page 3 for detail

As shown, there is no risk of interstitial condensation with this detail and it complies with the standards set out on BS5250.

Guarantee

TLX Gold, when correctly installed, is guaranteed for 25 years and is backed by comprehensive product liability insurance.

Issue 2015.12 page 1 | 3






Condensation risk analysis

		Interface Temp.	Dewpoint Temp.	Vapour Pressure (kPa)	Saturated V.P. (kPa)	Worst Cond. (g/m²)	Peak Buildup (g/m²)	Conden- sation
1	Outside surface resistance							
		1.4	-0.5	0.59	0.68			No
2	Clay tiles (BS5250)							
	, , ,	1.4	-0.5	0.59	0.68			No
3	Ventilated air gap							
		1.4	-0.5	0.59	0.68			No
4	TLX Gold							
		6.9	5.5	0.9	1.00			No
5	Unventilated air gap							
		8.9	6	0.93	1.14			No
6	Rafter Roll 32							
		18.9	9.1	1.15	2.18			No
7	Plasterboard							
		19.4	14.3	1.63	2.25			No
Q	Inside surface resistance							

8 Inside surface resistance



Well sealed ceiling

The condensation risk analysis given above shows that the temperature through the roof structure remains above the dew point, and there is no risk of interstitial condensation.

The calculation is based on the provision of a well-sealed ceiling, which prevents movement of warm moist air into the roof structure. It is essential when fitting TLX Gold to the outside of a roof structure, that action is also taken to improve the airtightness of the ceiling. A well-sealed ceiling requires the following:

- There should be no gaps in the internal lining of the ceiling, such as holes, cracks or gaps where services such as pipes or wires penetrate into the ceiling. Any gaps must be permanently sealed.
- The top of any cavity in a wall must be sealed.
- Loft hatches must have a compressed seal or draught excluder strip
- Recessed light fittings or down-lighters must incorporate a sealed box
- Edges of roof-lights should be permanently sealed.

Issue 2015.12 page 2 | 3





U-value calculation

TLX Gold Solution - 100 mm rafters breathable roof

	d (mm)	λlayer	λ bridge	fraction	R layer	R bridge	
Rse					0.100#		
Tiles (clay)	15	1.000					
Air layer ventilated	25	R-value					
TLX Gold	33	R-value	0.130	0.0300	0.850	0.254	
Air layer unventilated	10	R-value	0.130	0.117	0.303	0.077	
Glass wool (0.032)	50	0.032	0.130	0.117	1.562	0.385	
Plasterboard	12.5	0.179			0.070		
Rsi					0.100		
total	146 mm	(total roof thic	ckness)	2.985			

this resistance substitutes for Rse and the resistance of layers 5-6 because of the ventilated air layer (layer 5)

Total resistance: Upper limit: 2.679 Lower limit: 2.440 Ratio: 1.098 Average: 2.559 m²K/W

U-value (uncorrected) 0.391

U-value corrections

No fixings in layer 2 Air gaps in layer 2 $\Delta U = 0.000$ (level 0)

Total ΔU 0.000

U-value (corrected) 0.391

U-value (rounded) 0.39 W/m²K

Contact

TLX Insulation Ltd Moss Lane Blackrod Bolton Lancashire BL6 5JB

www.tlxinsulation.co.uk www.tlxgold.co.uk

TLX Gold hotline: 01204 674 730

Issue 2015.12 page 3 | 3